

*Remove C162 for no squelch beep.

*2 Remove to fix audio tone on UHF/VHF low channels (10 meter)