



Note: This is not the actual act of the Moonraker - but is nearly VCO is main difference.

If trouble is experienced with the VCO, check that Q31 is not partially turned on on RX. If it is, put  $4\text{K}7$  across R202.

# MOON RAKER MAJOR